ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0514, W0697, W0699, W0536	NA	Bagalagunte
Segment No	**Total Length (m)**	
14/C, W0514/S033104	115.14	

Segment Details

Seg No	Length (m)	Start Coordinates		End Coordinates		From	To
1	115.14	77.501507	13.056445	77.501158	13.055497	Maramma temple Back side	Devara Bhavi road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains at Bagalagunte Old Village &Surrounding of Maramma temple in Bagalagunte Ward No-14	2000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017-2018	Others	CC Drain and Covering
Tender	**Work Details**	**Job No / Work Code**
Tender		014 18-000227
Work Order No	**Work Order Date**	**Period of Extention**
EE:DD:WO:394:17-18	27/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/03/2018	26/03/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked / Released (Rs)
Ranganna + M		1902301.00
Phone No	**E-Mail ID**	
9845785427		

Zone: DASARAHALLI | Ward No: 14 | Ward Name: Bagalakunte | Street ID: W0514, W0697, W0699, W0536

Field Inspection Details

Number of Trees	Any Other Information	Name
1		Bagalagunte
Date of Inspection	**Remarks**	
04/10/2018	complete	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: DASARAHALLI Ward No: 14 Ward Name: Bagalakunte Street ID: W0514, W0697, W0699, W0536